



[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-9490; Directorate Identifier 2016-NE-26-AD; Amendment 39-18914; AD 2017-11-15]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for General Electric Company (GE) CF6-80C2L1F turbofan engines. This AD was prompted by a reduction in the life limit of the affected engines which is the result of a revised operating profile. This AD requires replacement of the high-pressure turbine (HPT) spacer/impeller, part number (P/N) 1539M12P02, at a newer, lower life limit. We are issuing this AD to correct the unsafe condition on these products.

DATES: This AD is effective [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES: See the For Further Information Contact section.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9490; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation,

Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Herman Mak, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7147; fax: 781-238-7199; email: herman.mak@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain GE CF6-80C2L1F turbofan engines. The NPRM published in the Federal Register on January 23, 2017 (82 FR 7734) (“the NPRM”). The NPRM was prompted by a reduction in the life limit of the affected engines which is the result of a revised operating profile. The NPRM proposed to require replacement of the HPT spacer/impeller, P/N 1539M12P02, at a newer, lower life limit. We are issuing this AD to prevent failure of the HPT spacer/impeller, uncontained release of the HPT spacer/impeller, damage to the engine, and damage to the airplane.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Request to Revise Compliance

GE Aviation requested that we indicate in the compliance section of this AD that the affected HPT spacer/impeller is installed on GE CF6-80C2L1F engines only. GE Aviation commented that this P/N impeller is also installed on other models of the CF6-80C2 engine.

We disagree. We believe that the applicability section is clear that this AD applies to GE CF6-80C2L1F turbofan engines with a HPT spacer/impeller, P/N 1539M12P02, installed. We did not change this AD.

Miscellaneous Comment

An individual commenter indicated that the proposal showed the FAA’s commitment to “staying on top of changes in the industry.” The commenter noted, however, that although GE has updated the life expectancy of this part, it may still be a long time before it needs to be replaced. The commenter indicated, therefore, that the FAA’s action may be “over zealous” and lead to “large scale waste.”

We disagree. We are issuing this AD to prevent failure of an engine rotating part, which could lead to failure of the part, uncontained release of the part, damage to the engine, and damage to the airplane. We did not change this AD.

Support for the NPRM

An individual commenter supported the NPRM.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD as proposed.

Costs of Compliance

We estimate that this AD affects 0 engines installed on airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

Estimated Costs

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement of HPT spacer/impeller at reduced life	0 work-hours x \$85 per hour = \$0	\$19,320 (pro-rated cost of part)	\$19,320	\$0

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2017-11-15 **General Electric Company**: Amendment 39-18914; Docket No. FAA-2016-9490; Directorate Identifier 2016-NE-26-AD.

(a) Effective Date

This AD is effective [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company (GE) CF6-80C2L1F turbofan engines with a high-pressure turbine (HPT) spacer/impeller, part number (P/N) 1539M12P02, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine/Turboprop Engine – Turbine Section.

(e) Unsafe Condition

This AD was prompted by a reduction in the life limit of the affected engines, which is the result of a revised operating profile. We are issuing this AD to prevent failure of the HPT spacer/impeller, uncontained release of the HPT spacer/impeller, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

After the effective date of this AD, replace the HPT spacer/impeller, P/N 1539M12P02, before it exceeds 18,000 flight cycles since new.

(g) Installation Prohibition

After the effective date of this AD, do not install an HPT spacer/impeller, P/N 1539M12P02, onto any engine, or return to service any engine with an HPT spacer/impeller, P/N 1539M12P02, installed, if the HPT spacer/impeller exceeds 18,000 flight cycles since new.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(i) Related Information

For more information about this AD, contact Herman Mak, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7147; fax: 781-238-7199; email: herman.mak@faa.gov.

(j) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on May 23, 2017.

Carlos A. Pestana,
Acting Manager, Engine & Propeller Directorate,
Aircraft Certification Service.

[FR Doc. 2017-11780 Filed: 6/7/2017 8:45 am; Publication Date: 6/8/2017]