



[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0648; Directorate Identifier 2017-CE-012-AD]

RIN 2120-AA64

Airworthiness Directives; PIAGGIO AERO INDUSTRIES S.p.A. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for PIAGGIO AERO INDUSTRIES S.p.A. Model P-180 airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as disbonding of the upper and lower metal skin from the honeycomb core on the elevator assembly and other flight control surfaces. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493-2251.

- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE, Washington, DC 20590.

- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact PIAGGIO AERO INDUSTRIES S.p.A – Continued Airworthiness, Via Pionieri e Aviatori d’Italia snc - 16154 Genova, Italy; Telephone: +39 010 0998046; Fax: None; email: airworthiness@piaggioaerospace.it; Internet: www.piaggioaerospace.it/en/customer-support#care. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0648; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include “Docket No. FAA-2017-0648; Directorate Identifier 2017-CE-012-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No.: 2017-0045, dated March 9, 2017 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

During a post flight inspection of a right hand (RH) elevator assembly, disbonding was detected on the upper and lower metal skin from the honeycomb core. Subsequent investigation identified that a manufacturing deficiency caused the detected disbonding and that other flight control surfaces could potentially be affected by the same deficiency.

This condition, if not detected and corrected, could reduce the structural stiffness of the flight control surface and downgrade its aerodynamic characteristics, possibly resulting in reduced control of the aeroplane.

To address this potential unsafe condition, Piaggio Aero Industries (PAI) issued Service Bulletin (SB) 80-0455 to provide inspection instructions.

For the reasons described above, this [EASA] AD requires repetitive inspections of the affected flight control assemblies and, depending on findings, repair or replacement. This [EASA] AD also requires reporting of the inspection result to PAI.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0648.

Related Service Information under 1 CFR part 51

PIAGGIO AERO INDUSTRIES S.p.A has issued PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin N.: 80-0455, dated: January 13, 2017.

The service information describes procedures for repetitive inspections to verify the structural integrity of the flight control assemblies. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section of this NPRM.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 103 products of U.S. registry. We also estimate that it will take 9 work-hours per product to comply with the basic requirements of the proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$78,795, or \$765 per product.

The scope of damage found in the required inspections could vary significantly from airplane to airplane. We have no way of determining how much damage may be found on each airplane or the cost to repair damaged parts on each airplane.

In addition, we have no way of knowing how many products may need replacement as a result of the required inspections. The following cost estimates were obtained directly from the manufacturer and we estimate that any necessary follow-on replacement actions would cost as follows:

(i) Control surface repair: 10 work-hours for a cost of \$850 per product.

(ii) Left Hand (LH) Forward Wing Flap Replacement: 4 work-hours and require parts costing \$30,079, for a total cost of \$30,419.

(iii) Right Hand (RH) Forward Wing Flap Replacement: 4 work-hours and require parts costing \$30,079, for a total cost of \$30,419.

(iv) LH Aileron Assembly: 7 work-hours and require parts costing \$40,715, for a total cost of \$41,310.

(v) RH Aileron Assembly: 7 work-hours and require parts costing \$86,050, for a total cost of \$86,645.

(vi) Main Wing LH Inboard Flap Assembly: 4 work-hours and require parts costing \$22,699, for a total cost of \$23,039.

(vii) Main Wing RH Inboard Flap Assembly: 4 work-hours and require parts costing \$22,699, for a total cost of \$23,039.

(viii) LH Elevator Assembly: 8 work-hours and require parts costing \$59,917, for a total cost of \$60,597.

(ix) RH Elevator Assembly: 8 work-hours and require parts costing \$59,917, for a total cost of \$60,597.

There is an additional 10 work-hours that may be required for post-repair or post-installation replacement of flight control surface adjustments and testing, for a total cost of \$850.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Piaggio Aero Industries S.p.A.: Docket No. FAA-2017-0648; Directorate Identifier 2017-CE-012-AD.

(a) Comments Due Date

We must receive comments by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

(b) Affected ADs

None.

(c) Applicability

This AD applies to PIAGGIO AERO INDUSTRIES S.p.A. P-180 airplanes, serial numbers 1002, 1004 through 1220, that are:

(1) equipped with flight control surfaces part numbers (P/Ns) and serial numbers (S/Ns) not listed in table 1 of PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin N.: 80-0455, dated: January 13, 2017; and

(2) certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 27: Flight Controls.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as disbonding of the upper and lower metal skin from the honeycomb core on the elevator assembly and other flight control surfaces. We are issuing this proposed AD to prevent structural stiffness of the flight control surface and the downgrade of its aerodynamic characteristics, resulting in reduced control.

(f) Actions and Compliance

Unless already done, do the actions in paragraphs (f)(1) through (8) of this AD. The parts affected by this AD are all left hand (LH) forward flaps, right hand (RH) forward flaps, main wing LH inboard flaps, main wing RH inboard flaps, LH ailerons, RH ailerons, LH elevators, and RH elevators, hereafter referred to as “affected control surface” in this AD.

(1) Within the next 50 hours time-in-service (TIS) after the effective date of this AD or within the next 200 hours TIS after the last coin tapping inspection of the affected control surface following PAI Non-Destructive Test Manual (NDTM) 180-MAN-0300-01107, Chapter 51-00-01; whichever occurs later, do a coin tapping inspection of each affected control surface. Repetitively thereafter inspect at the intervals specified in paragraphs (f)(3)(i) and (ii). Follow Part B of the Accomplishment Instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No.: 80-0455, dated January 13, 2017 (PAI SB No. 80-0455).

- (i) Do two repetitive inspections at intervals not to exceed 200 hours TIS; and
- (ii) Repetitively thereafter inspect at intervals not to exceed 600 hours TIS.

(2) If damage is found during any inspection required in paragraph (f)(1) of this AD, before further flight, repair or replace as necessary each damaged affected control surface following Part B and/or C of the Accomplishment Instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin (SB) No.: 80-0455, dated January 13, 2017.

(3) Within 50 hours TIS after the repair of an affected control surface as required by paragraph (f)(2) of this AD, do a coin tapping inspection of that repaired affected control surface. Repetitively thereafter inspect at the intervals specified in paragraphs (f)(3)(i) and (ii) of this AD. Follow the instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin (SB) No.: 80-0455, dated January 13, 2017.

(i) Do two repetitive inspections at intervals not to exceed 200 hours TIS; and

(ii) Repetitively thereafter inspect at intervals not to exceed 600 hours TIS.

(4) If damage is found during any inspection required in paragraph (f)(3) of this AD, before further flight, repair or replace as necessary each damaged affected control surface following the instructions in Part B and/or C of the Accomplishment Instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin (SB) No.: 80-0455, dated January 13, 2017.

(5) Repair of an affected control surface, as required by paragraph (f)(2) or (4) of this AD, does not constitute terminating action for repetitive inspections as required by this AD for that affected control surface, unless the FAA-approved repair instructions specify otherwise.

(6) Replacement of the affected part on an airplane with a part listed in Table 1 of PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin (SB) No.: 80-0455, dated January 13, 2017, constitutes terminating action for the repetitive inspections required by this AD for that part.

(7) You may incorporate the actions of PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin (SB) No.: 80-0455, dated January 13, 2017, into your FAA-approved Airplane Inspection Program (AIP) or maintenance program (instructions for continued airworthiness) to ensure the continuing airworthiness of each operated airplane.

(8) After the effective date of this AD, you may install on an airplane an affected control surface not listed in table 1 of PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin N.: 80-0455, dated: January 13, 2017, provided that before further flight after installation, the affected control surface has been inspected as specified in this AD and found airworthy.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2017-0045, dated March 9, 2017; and PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin (SB) No.: 80-0455, dated January 13, 2017; for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0648. For service information related to this AD, contact PIAGGIO AERO INDUSTRIES S.p.A – Continued Airworthiness, Via Pionieri e Aviatori d'Italia snc - 16154 Genova, Italy; Telephone: +39 010 0998046; Fax: None; email: airworthiness@piaggioaerospace.it; Internet: www.piaggioaerospace.it/en/customer-support#care. You may review this referenced

service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on June 21, 2017.

Pat Mullen,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 2017-13498 Filed: 6/28/2017 8:45 am; Publication Date: 6/29/2017]