#### DEPARTMENT OF TRANSPORTATION

**Federal Aviation Administration** 

**14 CFR Part 39** 

[Docket No. FAA-2025-3995; Project Identifier MCAI-2025-01653-T;

Amendment 39-23180; AD 2025-22-02

RIN 2120-AA64

Airworthiness Directives; MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain MHI RJ Aviation ULC (type certificate previously held by Bombardier, Inc.) Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2C11 (Regional Jet Series 550), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000) airplanes. This AD was prompted by reports of loose and missing bolts on the horizontal stabilizer (H-stab) anti-yaw steady fitting block. This AD requires repetitive torque checks of the H-stab anti-yaw steady fitting block bolts. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD is effective [INSERT DATE 15 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

The FAA must receive comments on this AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.
  - Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West
   Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC
   20590.

• Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m.,

- Monday through Friday, except Federal holidays.

  AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-3995; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

  Material Incorporated by Reference:
- For Transport Canada material identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888-663-3639; email TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca. You may find this material on the Transport Canada website at tc.canada.ca/en/aviation.
- You may view this material at the FAA, Airworthiness Products Section,

  Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on
  the availability of this material at the FAA, call 206-231-3195. It is also available at
  regulations.gov under Docket No. FAA-2025-3995.

FOR FURTHER INFORMATION CONTACT: Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; email: 9-avs-nyaco-cos@faa.gov.

#### **SUPPLEMENTARY INFORMATION:**

#### **Comments Invited**

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments using a method listed under the ADDRESSES section.

Include "Docket No. FAA-2025-3995; Project Identifier MCAI-2025-01653-T" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

#### **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; email: 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives

which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### Background

Transport Canada, which is the aviation authority for Canada, has issued

Transport Canada AD CF-2025-38, effective August 19, 2025 (Transport Canada AD

CF-2025-38) (also referred to as the MCAI), to correct an unsafe condition for certain

MHI RJ Aviation ULC Model CL-600-2C10 (Regional Jet Series 700, 701, and 702),

CL-600-2C11 (Regional Jet Series 550), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000)

airplanes. The MCAI states that during the completion of a maintenance task on the horizontal stabilizer, a bolt from the horizontal stabilizer anti-yaw steady fitting block was missing. The missing bolt and associated hardware were found lying on adjacent structure. Other bolts in the same bolt group on the anti-yaw steady fitting block were found to be loose. The anti-yaw steady fitting block bolts do not have a secondary locking feature. Loose or missing bolts on the anti-yaw steady fitting block when combined with a bird strike or gust loading may result in loss of the horizontal stabilizer.

The FAA is issuing this AD to address loose or missing bolts on the anti-yaw steady fitting block, which, when combined with a bird strike or gust loading, may result in loss of the horizontal stabilizer and consequent loss of control of the airplane.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA-2025-3995.

# Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed Transport Canada AD CF-2025-38, which specifies procedures for repetitive torque checks of the H-stab anti-yaw steady fitting block bolts. The torque check consists of inspecting the tightening torque on the four attachment bolts

that attach the steady block by replacing any bolt or nut that is loose or missing and then torquing all four bolts and nuts.

Transport Canada AD CF-2025-38 also specifies procedures to replace the H-Stab anti-yaw steady fitting block hardware. The replacement includes measuring four-hole diameters on the steady block and steady fitting; rework (ream) any hole diameter if required; and installing and torquing new hardware attachments (bolts, nuts, washers, and cotter pins) to create a double safety device on the hardware that attach the steady block to the steady fitting.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

### **FAA's Determination**

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

## Requirements of this AD

This AD requires accomplishing the actions specified in Transport Canada AD CF-2025-38 described previously, except for any differences identified as exceptions in the regulatory text of this AD. See "Differences Between This AD and the MCAI" for a discussion of the general differences included in this AD.

#### **Differences Between This AD and the MCAI**

Paragraph C. of the MCAI specifies to replace the H-stab anti-yaw steady fitting block hardware. The FAA is considering requiring this replacement, which would

terminate the repetitive torque checks required by this AD. However, the planned compliance time for the replacement would be long enough to allow for notice and opportunity for public comments on the merits of the replacement. This AD therefore seeks such comments, while allowing the replacement as an optional terminating action for the repetitive torque checks.

# **Explanation of Required Compliance Information**

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, Transport Canada AD CF-2025-38 is incorporated by reference in this AD. This AD requires compliance with Transport Canada AD CF-2025-38 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Material required by Transport Canada AD CF-2025-38 for compliance will be available at regulations.gov under Docket No. FAA-2025-3995 after this AD is published.

## Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for "good cause," finds that those procedures are "impracticable, unnecessary, or contrary to the public interest." Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has

found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because loose or missing bolts on the anti-yaw steady fitting block, when combined with a bird strike or gust loading, may result in loss of the horizontal stabilizer and consequent loss of control of the airplane. Additionally, the compliance time necessary to address this unsafe condition, as set forth in this AD, is shorter than the time necessary for the public to comment and for publication of the final rule.

Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

### Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

### **Costs of Compliance**

The FAA estimates that this AD affects 597 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

### **Estimated costs for required actions**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 6 work-hours X \$85 per hour = \$510	\$0	Up to \$510	Up to \$304,470

### **Estimated costs for optional actions**

Labor cost	Parts cost	Cost per product
7 work-hour X \$85 per hour = \$595	\$27	\$622

The FAA estimates the following costs to do any necessary on-condition action that would be required based on the results of any required actions. The FAA has no way of determining the number of aircraft that might need this on-condition:

### **Estimated costs of on-condition actions**

Labor cost	Parts cost	Cost per product
1 work-hour X \$85 per hour = \$85	Up to \$28	Up to \$113

#### **Authority for this Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the

national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

# List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### **The Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### **PART 39 - AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

### 2025-22-02 MHI RJ Aviation ULC (Type Certificate Previously Held by

**Bombardier, Inc.):** Amendment 39-23180; Docket No. FAA-2025-3995; Project Identifier MCAI-2025-01653-T.

## (a) Effective Date

This airworthiness directive (AD) is effective [INSERT DATE 15 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

# (b) Affected ADs

None.

# (c) Applicability

This AD applies to MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.) Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-

2C11 (Regional Jet Series 550), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000) airplanes, certificated in any category, as identified in Transport Canada AD CF-2025-38, effective August 19, 2025 (Transport Canada AD CF-2025-38).

# (d) Subject

Air Transport Association (ATA) of America Code 55, Stabilizers.

## (e) Unsafe Condition

This AD was prompted by reports of loose and missing bolts on the horizontal stabilizer anti-yaw steady fitting block. The FAA is issuing this AD to address loose or missing bolts on the anti-yaw steady fitting block, which, when combined with a bird strike or gust loading, may result in loss of the horizontal stabilizer and consequent loss of control of the airplane.

### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

## (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada AD CF-2025-38.

# (h) Exception to Transport Canada AD CF-2025-38

- (1) Where Transport Canada AD CF-2025-38 refers to its effective date, this AD requires using the effective date of this AD.
- (2) Where Transport Canada AD CF-2025-38 refers to hours air time, this AD requires using flight hours.
- (3) Where Transport Canada AD CF-2025-38 refers to the effective date of Transport Canada AD CF-2024-24 (July 4, 2024), this AD requires using the effective date of this AD.

- (4) Where paragraph B. of Transport Canada AD CF-2025-38 specifies to repeat the torques check "every 2200 hours air time from the previous inspection", for this AD, replace that text with "at intervals not to exceed 2,200 flight hours".
  - (5) This AD does not adopt paragraph C. of Transport Canada AD CF-2025-38.

### (i) Additional AD Provisions

The following provisions also apply to this AD:

- (1) Alternative Methods of Compliance (AMOCs): The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.
- (2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or MHI RJ Aviation ULC's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

# (j) Additional Information

For more information about this AD, contact Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; email: 9-avs-nyaco-cos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference

(IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD,

unless this AD specifies otherwise.

(i) Transport Canada AD CF-2025-38, effective August 19, 2025.

(ii) [Reserved]

(3) For Transport Canada material identified in this AD, contact Transport

Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean,

Ontario K1A 0N5, Canada; telephone 888-663-3639; email TC. Airworthiness Directives-

Consignesdenavigabilite.TC@tc.gc.ca. You may find this material on the Transport

Canada website at tc.canada.ca/en/aviation.

(4) You may view this material at the FAA, Airworthiness Products Section,

Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on

the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records

Administration (NARA). For information on the availability of this material at NARA,

visit www.archives.gov/federal-register/cfr/ibr-locations or email

fr.inspection@nara.gov.

Issued on October 30, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division,

Aircraft Certification Service.

[FR Doc. 2025-19784 Filed: 11/3/2025 8:45 am; Publication Date: 11/5/2025]