



This document is scheduled to be published in the Federal Register on 10/23/2014 and available online at <http://federalregister.gov/a/2014-25240>, and on [FDsys.gov](http://FDsys.gov)

**[4910-13]**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 25**

**[Docket No. FAA-2014-0666; Special Conditions No. 25-566-SC]**

**Special Conditions: Bombardier Aerospace, Models BD-500-1A10 and BD-500-1A11 Series Airplanes; Isolation or Airplane Electronic System Security**

**Protection from Unauthorized Internal Access**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final special conditions; corrections.

**SUMMARY:** This document corrects two errors that appeared in Docket No. FAA-2014-0666, Special Conditions No. 25-566-SC, which was published in the Federal Register on September 12, 2014 (79 FR 54572). There is an error in the header information and in one instance of one of the airplane model numbers in the publication.

**DATES:** The effective date of this correction is **[insert date of publication in the Federal Register]**.

**FOR FURTHER INFORMATION CONTACT:** Varun Khanna, FAA, Airplane and Flight Crew Interface Branch, ANM-111, Transport Airplane Directorate, Aircraft Certification Service, 1601 Lind Avenue SW., Renton, Washington, 98057-3356; telephone (425) 227-1298; facsimile (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** On September 12, 2014, the Federal Register published document designated as “Docket No. FAA-2014-0666, Notice No. 25-566-SC,” (79 FR 54572). The document issued special conditions pertaining to network security in the

digital systems architecture, access from internal sources, on the BD-500-1A10 and BD-500-1A11 series airplanes.

As published, the document contained two errors:

1. In the header of the document, “Notice No.” should have been “Special Conditions No.”
2. In one instance, the airplane model number was published as “BD-500-1A1” instead of “BD-500-1A11.”

### **Correction**

In Final special conditions document (FR Doc. 2014-21788), published on September 12, 2014 (79 FR 54572), make the following corrections:

1. On page 54572, third column in the header information, correct “Notice No.” to read “Special Conditions No.”
2. On page 54574, first column, last line in the introductory text of the section titled, “The Special Conditions,” correct “BD-500-1A1” to read “BD-500-1A11.”

Issued in Renton, Washington on October 16, 2014.

Michael Kaszycki  
Acting Manager, Transport Airplane Directorate  
Aircraft Certification Service

[FR Doc. 2014-25240 Filed 10/22/2014 at 8:45 am; Publication Date: 10/23/2014]