



This document is scheduled to be published in the Federal Register on 06/30/2016 and available online at <http://federalregister.gov/a/C1-2016-14474>, and on FDsys.gov

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA 2015 7491; Directorate Identifier 2015-NE-39-AD; Amendment 39-18569; AD 2016-13-05]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

Correction

In rule document 2016-14474, beginning on page 41208 in the issue of Friday, June 24, 2016, make the following correction:

§ 39.13 [Corrected]

On page 41210, in the table titled “Table 1 to Paragraph (e) – HPC Stage 8-10 Spool S/Ns”, the first row of the table should appear as follows:

1844M90G01	GWN005MF	GWNBK753	GWNBS077	GWNBS497	GWNBS724
	GWN005MG	GWNBK754	GWNBS078	GWNBS499	GWNBS794
	GWN0087M	GWNBK841	GWNBS079	GWNBS500	GWNBS810
	GWN0087N	GWNBK842	GWNBS080	GWNBS501	GWNBS811
	GWN00DGK	GWNBK843	GWNBS081	GWNBS502	GWNBS812
	GWN00DGL	GWNBK844	GWNBS157	GWNBS609	GWNBS813
	GWNBK992	GWNBK952	GWNBS158	GWNBS610	GWNBS814
	GWNBK667	GWNBK953	GWNBS159	GWNBS611	GWNBS910
	GWNBK674	GWNBK954	GWNBS160	GWNBS612	GWNBS911
	GWNBK675	GWNBK955	GWNBS266	GWNBS613	GWNBS912
	GWNBK743	GWNBK956	GWNBS267	GWNBS614	GWNBS914
	GWNBK744	GWNBK957	GWNBS268	GWNBS721	GWNBS915
	GWNBK751	GWNBK958	GWNBS269	GWNBS722	GWNBS982
	GWNBK752	GWNBK959	GWNBS270	GWNBS723	GWNBS983

[FR Doc. C1-2016-14474 Filed: 6/29/2016 8:45 am; Publication Date: 6/30/2016]