



[4910-13]

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**Supplemental Type Certificates SA401SW, SE325SW, SE419SW (Original Product Type Certificate Numbers A1CE, 2A13, 1A15, 1A10, 2A3, 273, E5CE, 3E1, E246, and E267)**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Request for information on holder of supplemental type certificates (STC's) prior to FAA declaring STC abandoned.

**SUMMARY:** This Notice requests the current holder(s)—or their heirs—of STC's SA401SW, Full flow oil filter; SE325SW, Full flow oil filter; SE419SW, Full flow oil filter; come forward and identify themselves before the FAA declares these STC's abandoned.

**DATES:** We must receive all correspondence by [INSERT DATE 180 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**FOR FURTHER INFORMATION CONTACT:** Send all correspondence on this issue to: Federal Aviation Administration, Chicago Aircraft Certification Office, 2300 East Devon Avenue, Room 107, Des Plaines, IL, 60018. **ATTN:** JoWanna Jenkins, ACE-116C1. All letters must be certified and signed. You may also contact Ms. Jenkins by phone at (847) 294-7145, or electronically at [jowanna.jenkins@faa.gov](mailto:jowanna.jenkins@faa.gov).

## **SUPPLEMENTARY INFORMATION:**

### **Background**

The FAA has received a third party request for the release of data for STC's SA401SW, SE325SW, and SE419SW under the provisions the Freedom of Information Act (FOIA), 5 U.S.C. 552. The FAA cannot release the requested data without the permission of the STC holder. The STC holder last listed on the certificate record is the Superior Flow Company, Division of A & E Manufacturing Inc.; Detroit, MI. The FAA has been unsuccessful in contacting the Superior Flow Company by telephone, email, and/or certified mail. There has been no activity with this STC holder for more than 3 years.

### **Information Requested**

If you are the owner, or heir, or a transferee of STC's SA401SW, SE325SW, or SE419SW, or have any knowledge regarding who may now hold STC's SA401SW, SE325SW, or SE419SW, please contact JoWanna Jenkins using a method described in the FOR FURTHER INFORMATION CONTACT section of this notice. If you are the owner of STC's SA401SW, SE325SW, or SE419SW, you must provide a notarized copy of your Government issued identification (ID) with a letter and background establishing your ownership of the STC's and/or relationship as the heir to the deceased holder of the STC's (if that is the case).

### **Conclusion**

If we do not receive any response by [INSERT DATE 180 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER], we will consider STC's SA401SW, SE325SW, and SE419SW abandoned and we will accordingly proceed with

the release of the requested data. **This notice is issued in accordance with Section 302 of the FAA Modernization and Reform Act of 2012, Public Law 112-95, <https://www.gpo.gov/fdsys/pkg/PLAW-112publ95/content-detail.html>. Partially codified as Title 49 of the United States Code (49 U.S.C.) Section 44704(a)(5).**

Issued in Kansas City, MO on April 20, 2017.

Mel Johnson,  
Acting Manager, Small Airplane Directorate,  
Aircraft Certification Service.  
[FR Doc. 2017-08753 Filed: 4/28/2017 8:45 am; Publication Date: 5/1/2017]