



## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

**[Docket No. FAA-2025-0215; Project Identifier MCAI-2024-00347-T]**

**RIN 2120-AA64**

### **Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes. This proposed AD was prompted by events where the cargo bottle fail caution message was displayed. This proposed AD would require replacing affected low rate discharge (LRD) bottles, inspecting extinguishing discharge lines and tubes, and replacing extinguishing discharge lines and tubes, as applicable, and would also prohibit the installation of affected LRD bottles, as specified in a Transport Canada AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- Fax: 202-493-2251.

- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0215; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

- For Transport Canada material identified in this proposed AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888-663-3639; email [TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca](mailto:TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca); website [tc.canada.ca/en/aviation](https://tc.canada.ca/en/aviation). It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0215.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

**FOR FURTHER INFORMATION CONTACT:** Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; email: [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

## **SUPPLEMENTARY INFORMATION:**

### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the ADDRESSES section. Include “Docket No. FAA-2025-0215; Project Identifier MCAI-2024-00347-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

### **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; email: 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA

receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

## **Background**

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2024-23, dated June 18, 2024 (Transport Canada AD CF-2024-23) (also referred to as the MCAI), to correct an unsafe condition for all Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes. The MCAI states there were events where the cargo bottle fail caution message was displayed during flight resulting in diversions. Investigations found the LRD bottle was depleted of extinguishing agent. Further investigation revealed the LRD bottle metering device could be loose allowing extinguishing agent to escape resulting in loss or degraded capability of the cargo extinguishing system. The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0215.

## **Material Incorporated by Reference Under 1 CFR Part 51**

Transport Canada AD CF-2024-23 specifies procedures for verifying aircraft technical records to determine if an affected part (any LRD bottle having part number 475086-1, 475124-1 or 475087-1 with certain serial numbers, unless the LRD bottle is marked with an encircled 'C' on the LRD bottle label) is installed on the airplane, replacing affected LRD bottles, and replacing extinguishing discharge lines and tubes, as applicable. Transport Canada AD CF-2024-23 also prohibits the installation of affected parts. The detailed visual inspections of the discharge lines and tubes, in multiple compartments, include checking discharge heads and distribution tubes for signs of residue and corrosion. This material is reasonably available because the interested parties

have access to it through their normal course of business or by the means identified in the ADDRESSES section.

### **FAA's Determination**

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

### **Proposed AD Requirements in this NPRM**

This proposed AD would require accomplishing the actions specified in Transport Canada AD CF-2024-23 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

### **Explanation of Required Compliance Information**

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate Transport Canada AD CF-2024-23 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with Transport Canada AD CF-2024-23 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Material required by Transport Canada AD CF-2024-23 for compliance will be available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0215 after the FAA final rule is published.

## Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 74 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

### Estimated costs for required actions

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
16 work-hours X \$85 per hour = \$1,360	\$0	\$1,360	\$100,640

### Estimated costs of on-condition actions

Labor cost	Parts cost	Cost per product
10 work-hours X \$85 per hour = \$850	Up to \$17,368	Up to \$18,218

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

## Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### **The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### **PART 39 - AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(f), 40113, 44701.

#### **§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.):** Docket No. FAA-2025-0215; Project Identifier MCAI-2024-00347-T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD-500-1A10 and BD-500-1A11 airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 26, Fire protection.

**(e) Unsafe Condition**

This AD was prompted by events where the cargo bottle fail caution message was displayed due to the depletion of extinguishing agent from the low rate discharge bottle. The FAA is issuing this AD to address the unsafe condition, which if not addressed, could result in loss or degraded capability of the cargo extinguishing system.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraphs (h), (i) and (j) of this AD: Comply with all required actions and compliance times specified in, and in accordance with Transport Canada AD CF-2024-23, dated June 18, 2024 (Transport Canada AD CF-2024-23).

**(h) Exception to Transport Canada AD CF-2024-23**

(1) Where Transport Canada AD CF-2024-23 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where the definition of “Affected Part” in Transport Canada AD CF-2024-23 specifies “a serial number listed in the Applicability Section of the ACLP SB,” this AD requires replacing that text with “a serial number listed in the Applicability Section of SB BD500-262010, Issue 001, dated 30 April 2024.”

(3) Where the paragraph B. of Part 1 in Transport Canada AD CF-2024-23 specifies “in accordance with the procedure in Section 2 of the Accomplishment Instructions of the ACLP SB,” this AD requires replacing that text with “in accordance with the “Procedure” section of the Accomplishment Instructions of the ACLP SB.”

**(i) No Reporting Requirement**

Although the material referenced in Transport Canada AD CF-2024-23 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(j) Additional AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of AIR-520, Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, AIR-520, Continued Operational Safety Branch, FAA; or

Transport Canada; or Airbus Canada Limited Partnership's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraphs (i) and (j)(2) of this AD, if any material contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

**(k) Additional Information**

For more information about this AD, contact Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; email: 9-avs-nyaco-cos@faa.gov.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada AD CF-2024-23, dated June 18, 2024.

(ii) [Reserved]

(3) For Transport Canada material identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean,

Ontario K1A 0N5, Canada; telephone 888-663-3639; email TC.AirworthinessDirectives-  
Consignesdenavigabilite.TC@tc.gc.ca; website [tc.canada.ca/en/aviation](http://tc.canada.ca/en/aviation).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on February 25, 2025.

Suzanne Masterson,  
Deputy Director, Integrated Certificate Management Division,  
Aircraft Certification Service.  
[FR Doc. 2025-03375 Filed: 2/28/2025 8:45 am; Publication Date: 3/3/2025]